

Education Suruhanu

Memorandum

Office of the Adequate Education Suruhanu (Ombudsman) 126 Ricardo J. Bordallo Governor's Complex, Adelup P.O. Box 2950 Hagatna, Guam 96932

Telephone: (671) 475-9130 · Fax: (671) 477-4826 Email: <u>educationsuruhanu@guam.gov</u> Web Page Address: www.guamlegislature.com



001 25 M 8: 52

October 11, 2010

TO:	Superintendent of Education
FROM:	Education Suruhanu
SUBJECT:	Chief Brodie Elementary School Inspection

Håfa Adai Dr. Bretania Underwood:

Attached to this memorandum is a report identifying various discrepancies discovered during an inspection of the Chief Brodie Elementary School that took place on October 5, 2010. I strongly recommend that GDOE address the discrepancies identified and rectify them immediately in order to come into compliance with the various provisions of the Fourteen (14) Points of P.L. 28-45, the School Sanitation Code, and/or other laws or regulations of the various regulatory agencies. Please be advised that not all classrooms or school facilities were inspected. Therefore, GDOE is highly encouraged to asses all other classrooms and school facilities in order to identify any other discrepancies and perform corrective action as necessary.

In addition, it was discovered that the school's fire alarm system remains inoperable and that the temporary fire watch program is still in effect. Because the temporary fire watch program has been in effect for an extended period of time, I am respectfully requesting a detailed report prepared by the necessary parties identifying the action taken or to be taken to bring the school's fire alarm system into full operation including but not limited to the status of any procurement for the repair, maintenance, and/or servicing of the schools' fire alarm systems and the expected date when such work to repair the fire alarm system would begin. Please provide the requested information concerning this issue to my office within five days of your office's receipt of this memorandum.

Please submit to my office, in writing, GDOE's efforts to rectify each of the discrepancies identified in the inspection report, including but not limited to measures taken or to be taken to rectify each discrepancy and a proposed date when such discrepancy was rectified or would be rectified.

If you have questions, please do not hesitate to contact my office.

Si Yu'os Ma'åse',

Dominic Terlaje

Attachment: OES Inspection report

cc: Honorable Speaker, 30th Guam Legislature GEB Chief Brodie Elementary School Administration Billy Cruz, GDOE Maintenance Manager (via email) Ron Carandang, DPHSS DEH Fire Chief, GFD Pat Mason, AGO

Dat 2 53 6-10-0867

Government of Guam Office of the Education Suruhanu (OES) School Inspection Report

Έ.

٠

PUBLIC LAW 28-45: 14 POINTS COMPLIANCE										
School Representative: Ms. Diaz, Principal									Name of School:	
Dat	e of inspection: Oc	tober f	5, 2010							-
	ather Condition: S OE custodians: No					ound 2 n.m.		• •	Chi	ef Brodie Elementary
	OL customins. 10		ivate castoaiar i	chuor arr	1100 41					
	·····							<u> </u>	· · · · · · · · · · · · · · · · · · ·	·····
\vdash					-		1 · · · ·	· · · · · · · · · · · · · · · · · · ·		
			Citation PH=DPHSS		D e m					
	Loc.	14 pt.	F=Fire Dept E=EPA	Date	е. Г	Description of Finding		Comments		Recommendations
		1	S≈Suruhanu		∘, L t		· .			
		- 1			3					
	Boys and Girls common use restrooms located near main office.	i&I	S	10/5/10		 Boys: Toilet stall without toilet tissue. Boys: Toilet tissue dispenser in disrepair. Girls: Toilet tissue dispenser in disrepair. Girls: Sink may not be properly secured in place. (Note: GDOE maintenance personnel removed the sink shortly after it was reported in disrepair.) 	stocked with th good repair. Sc employ a GDO school personn necessary. A re is being proper various other p provided custo always be avail	e necessary sanitary supp	ilies, maintained in nat they no longer various other the restrooms as t is provided and it school aides and ng assigned to nel may not ustodian should be	The necessary janitorial/custodial GDOE personnel should be assigned to the school as soon as possible to ensure that the school's custodial services and needs are being met during the school day.
	Library	f&l	S	10/5/10	N/A	Room is not properly air conditioned or properly ventilated in which the sensible air temperature is no greater than 78 °F.	classroom, it is learning activit ventilated to en learning enviro mechanical ver working order. The right A/C operation but th approximately no students pre	brary may not necessarily a room where students o ies and as such, it should usure students are provide mment when using the lib ntilation is provided it sha The left A/C blows warn unit is not working. Fou he room temperature meas 82 °F with a humidity reases resent. The librarian also in the room become warmer to ternoon.	ften engage in be properly d a comfortable rary. When Il be in good m air and is noisy. tr floor fans are in sured uding of 52% with ndicated that the	Assess the A/C unit immediately and either repair or replace it accordingly. If the A/C units cannot be addressed and rectified immediately, additional fans or portable air conditioning units should be provided as necessary.

Government of Guam Office of the Education Suruhanu (OES) School Inspection Report

:

•

5

						PUBLIC LAW 28	-45: 14 POINTS COMPLIANCE		
	ol Representative: of inspection: Oc			-	•	· · · · · · · · · · · · · · · · · · ·		Name of School:	
	ther Condition: S			ome cloud		Chief Brodie Elementary			
GDC	DE custodians: No	one. Pr	ivate custodial v	vendor arr	ives ar	ound 2 p.m.			
-	Loc.	14 pt.	Citation PH=DPHSS F=Fire Dept E=EPA S=Suruhanu	Date	D e m e r i t s	Description of Finding	Comments	Recommendations	
	13	f&1	S	10/5/10	N/A	in which the sensible air temperature is no greater than 78	When mechanical ventilation is provided it shall b working order. According to the teacher, the right unit has not worked for the past few years. The le unit works but is not cooling properly. The teacher indicated that such A/C units has not been cooling since May 2010. The room temperature measured approximately 83 °F with a humidity reading of 62 no students present.	ft A/C room cannot be improved immediately, the students should be re-located to a more suitable properly room.	
	Water fountain near room 8.	1	S	10/5/10	N/A	Observed water fountain not working.	Drinking fountains are required to be kept clean a good repair. In addition a sufficient amount of du fountains are necessary in order to accommodate to student population.	rinking If the water fountain is not necessary in order to	
	14	f&1	S	10/5/10	N/A	Right A/C unit is in operation but is noisy.	When mechanical ventilation is provided it shall b working order. The temperature of the room is comfortable but the right A/C unit is noisy.	he in good A/C unit should be assessed to determine the cause of the noise.	
	Book room	1	S	10/5/10	N/A	Termite activity.	According to school officials, termite activity is p the book room.	resent in Contact pest control services vendor and have affected areas treated immediately and as often as is necessary. Ensure that proof of any such pest control services provided is made available upon request. Proof of services should indicate the date of treatment, the area treated, the targeted pest, insect, or vector, the type of chemical used, and any other pertinent information.	

Government of Guam Office of the Education Suruhanu (OES) School Inspection Report

•

.

			· · · · · · · · · · · · · · · · · · ·			PUBLIC LAW 28	-45: 14 POINT	'S COMPLIANC	E		· · · · · · · · · · · · · · · · · · ·
	ol Representative of inspection: Oc		· · ·					-			Name of School:
	ther Condition: S E custodians: No					ound 2 p.m.				Ch	ief Brodie Elementary
				· .	D				1		
1			Citation PH=DPHSS		e m						
	Loc.	14 pt.	F=Fire Dept E=EPA S=Suruhanu	Date	e 1 t 5	Description of Finding		Comm	ients		Recommendations
	Cafeteria	1	S	10/5/10	N/A	Three A/C units are inoperable.	1	ical ventilation i ntained in good	-	ed, it shall be kept order.	Identify and repair or replace any such A/C unit found to be in disrepair.
	Campus	1	S	10/5/10	N/A	Fire alarm system not operational.	system. Acco	rding to GFD, th be continued un	e tempor	a working fire alarm ary Fire Watch hool's fire alarm	Although GFD has authorized the use of a Fire Watch Program as temporary fire prevention measure, I strongly encourage GDOE to begin repairing, replacing, and/or upgrading each school's fire alarm immediately. Please provide the status of GDOE's efforts to rectify the school's alarm system, when any such work is expected to begin, and the time frame in which it would take t complete any such work.