

Office of the Adequate Education Suruhanu 126 Ricardo J. Bordallo Governor's Complex, Adelup P.O. Box 2950 Hagatna, Guam 96932

Telephone: (671) 475-9130 · Fax: (671) 477-4826 Email: <u>educationsuruhanu@guam.gov</u> Web Address: www.guamlegislature.com

January \$

20 NO



Dominic Terlaje Education Suruhanu

To:

Superintendent of Education

From:

Education Suruhanu

Subject:

Ordot Chalan Pago Elementary School Inspection

30-10-0129

Dear Dr. Bretania Underwood:

An inspection of the Ordot Chalan Pago Elementary School campus occurred on January 29, 2010. The agencies that participated in the inspection were the Department of Public Health and Social Services (DPHSS), the Guam Environmental Protection Agency (GEPA), and our office. As a result of the inspection, DPHSS issued a letter grade "A" for the school building with a total of eight (8) demerits. In addition, DPHSS issued a letter grade "A" for the Cafeteria with four (4) demerits. GEPA also issued an inspection report detailing the discrepancies discovered. However, GEPA does not issue demerit points for such discrepancies.

P.L. 28-45 § 4 (12) (1) of the Adequate Public Education Act (the Act), requires Public Schools to provide a healthful, safe, and sanitary learning environment. However, the Act does not provide for a time frame to come into compliance for the noted discrepancies/violations. As such, GDOE should rectify such discrepancies/violations immediately. In addition, Title 10 G.C.A. Chapter 21 states that violations identified in a DPHSS inspection report must be corrected within a specific time frame. When an inspection yields a demerit score of 20 or less, all violations of two (2) or four (4) demerit points must be corrected within a period of time not to exceed 30 days. See 10 G.C.A. § 21107 (2) (a).

The school building received a demerit score of eight (8) and the Cafeteria received a demerit score of four (4) therefore, the two (2) and four (4) demerit point items listed in the DPHSS inspection report must be corrected within 30 days from the date of the inspection. Although there is no reported time frame in which to correct the discrepancies noted by GEPA, any such discrepancies should be corrected immediately.

I strongly recommend that GDOE address all discrepancies/violations identified in the inspection reports and rectify them immediately in order to come into compliance with the various regulatory agency codes, with the various provisions of the Fourteen (14) Points of the Act, and/or with any other applicable laws or rules. Because not all the school's classrooms or school's facilities were inspected, GDOE is highly encouraged to assess all other classrooms and school facilities in order to identify any other discrepancies and perform the necessary corrective action.

Please submit to my office in writing, GDOE's plan to rectify each of the discrepancies/violations identified in any such inspection report, including but not limited to the measure taken or to be taken to rectify the discrepancy/violation and the date when such discrepancy/violation was rectified or would be rectified.

Respectfully submitted,

. Dominic Terlaje

Attachment: Inspection Report

cc:

Honorable Speaker, 30th Guam Legislature Chairman, GEPB Billy Cruz, GDOE Facilities and Maintenance Manager (via email) Ordot School Principal (via email)

PUBLIC LAW 28-45: 14 POINTS COMPLIANCE

School Representative: Ms. Duenas, Principal
Date and Time of Inspection: January 29, 2010
Weather Condition: Warm, sunny, and dry.
Letter Grade: School building: "A" eight demerits / Cafeteria: "A" four demerits

Name of School: ORDOT CHALAN PAGO

Location	14 Point at issue (a-n)	Type of Citation (PH=DPHSS, F=Fire Dept, E=EPA, S=Suruhanu	Date of Citation	D e m e r i t	Description of Finding	Comments	Recommendations	
Campus	1	PH & S	1/29/10	2	Overgrown vegetation/Several bamboo from the adjacent landowner's property have spread on school property.	P.L. 28-45 § 4 (12) (I) requires schools to provide a healthful, safe, and sanitary learning environment. The Department of Public Health (DPH) School Sanitation Code (SSC) requires that school grounds to be free of overgrown vegetation. Village Mayors are mandated by law to provide grounds maintenance services to the schools. The Principal indicated that the Mayor is scheduled to meet with the landowner to address this matter.	Address and rectify immediately in order to cointo compliance with the law.	ome
6,7,8, & 9	arra d	PH & S	1/29/10	2	1 0 0 3 Cl 1 Cd 1 Willions 10 Ollis 11 lill dark	P.L. 28-45 § 4 (12) (I) requires schools to provide a healthful, safe, and sanitary learning environment. The SSC requires school floors to be kept clean and in good repair.	Address and rectify immediately in order to co into compliance with the law. Floors should a properly cleaned as necessary. Request the pr custodial vendor to perform such work after so hours.	be rivate
Campus	Treat	S	1/29/10	N/A	Fire alarm system inoperable	P.L. 28-45 § 4 (12) (1) requires schools to provide a healthful, safe, and sanitary learning environment.	Approved Fire Watch Program must remain in effect.	n

PUBLIC LAW 28-45: 14 POINTS COMPLIANCE School Representative: Ms. Duenas, Principal Date and Time of Inspection: January 29, 2010 Weather Condition: Warm, sunny, and dry. Letter Grade: School building: "A" eight demerits / Cafeteria: "A" four demerits

Name of School: ORDOT CHALAN PAGO

							T			[
Location	14 Point at issue (a-n)	Type of Citation (PH=DPHSS, F=Fire Dept, E=EPA, S=Suruhanu	Date of Citation	D e m e r i t	Description of Finding		Comment	S	Recommendations	
Campus	I	PH & S	1/29/10	4	Observed that the annual service date for several of the fire extinguishers expired several months ago.	healthful, safe, SSC requires f they be in good GDOE that suc Although the s extinguishers, adequate numb extinguishers in department of indicated that	and sanitary learn fire extinguishers of d working order. the matter must be school had six pro- the remainder we per of properly wo must be provided		schools. Proper planning and schedul	and the see for all fire reminders to ual service guishers. In add coordinate in advance of ishers or in disrepair in int of properly ole in the ling should be of working int safety is antily the annual
Cafeteria	I	PH & S	1/29/10	2	Walk in chiller door is in disrepair. (Not cooling properly)	healthful, safe, Section 7.201 Social Service and Drinking I	, and sanitary lear of the Departmen s Rule sand Regul Establishments (E	schools to provide a ning environment. t of Public Health and lations relative to Eating ating and Drinking maintained in good	Address and rectify immediately in or into compliance with the law. Repair walk in chiller door to ensure that the g maintains the proper temperature of 4	and/or replace chill unit

PUBLIC LAW 28-45: 14 POINTS COMPLIANCE

Weather Condition: Warm, sunny, and dry. Letter Grade: School building: "A" eight demerits / Cafeteria: "A" four demerits

School Representative: Ms. Duenas, Principal

Date and Time of Inspection: January 29, 2010

Name of School: ORDOT CHALAN PAGO

Location	14 Point at issue (a-n)	Type of Citation (PH=DPHSS, F=Fire Dept, E=EPA, S=Suruhanu	Date of Citation	D e m e r i t	Description of Finding	Comments	Recommendations
Cafeteria	1	PH & S	1/29/10	2	Observed burnt out light bulbs throughout the cafeteria dining area.	P.L. 28-45 § 4 (12) (1) requires schools to provide a healthful, safe, and sanitary learning environment. Adequate lighting should be provided and good working order. The school is experiencing difficulty in replacing many of the dining hall light bulbs as necessary because the light fixtures are located high in the ceiling which requires equipment other than a ladder to reach such fixtures.	Address and rectify immediately in order to co- into compliance with the law. Replace burnt or light bulbs as necessary. DOE should provide proper equipment for the safe removal and installation of such light bulbs.
Campus	1	E&S	1/29/10	N/A	Observed stockpiling of green waste along parking lot fence.	P.L. 28-45 § 4 (12) (1) requires schools to provide a healthful, safe, and sanitary learning environment. GEPA requires green waste to be removed from campus and disposed of properly.	Address and rectify immediately in order to co into compliance with the law.
Ponding Basins	l	E&S	1/29/10	1	Observed over grown vegetation located within the ponding basin area.	P.L. 28-45 § 4 (12) (1) requires schools to provide a healthful, safe, and sanitary learning environment. GEPA requires ponding basins to be properly maintained.	Address and rectify immediately in order to co into compliance with the law. Contact the par authorized to enter the ponding basin and requithat the area be maintained on a regular basis a required by GEPA.
Area behind room 18 and 16	l	E&S	1/29/10	N/A	Observed two cleanout covers missing.	P.L. 28-45 § 4 (12) (1) requires schools to provide a healthful, safe, and sanitary learning environment. GEPA requires such cleanout system to be in good repair.	Address and rectify immediately in order to co into compliance with the law. Repair and/or replace to ensure that such access system is presealed.
Outside library	l	E&S	1/29/10	N/A	Observed standing rain water.	P.L. 28-45 § 4 (12) (1) requires schools to provide a healthful, safe, and sanitary learning environment. GEPA requires standing water to be removed and that sources causing standing rain water be rectified.	Address and rectify immediately in order to co into compliance with the law. Remove any standing rain water as necessary. Standing rai water may also present other issues such as mosquito breeding and slip and fall hazards.

		7 7 :			. :	PUBLIC LAW 28-45: 14	POINTS COM	IPLIANCE			
Date Weat	ol Representative: M and Time of Inspect ther Condition: War r Grade: School buil	ion: Janu m, sunny	ary 29, 2010 , and dry.	' Cafeteria: "A	" four (lemerits			Name of Scho	ol: ORDOT CHA	LAN
	Location	14 Point at issue (a-n)	Type of Citation (PH=DPHSS, F=Fire Dept, E=EPA, S=Suruhanu	Date of Citation	D e m e r i t s	Description of Finding		Comment	S	Recommendations	
	Area near the front exit gate	1	E&S	1/29/10	N/A	Missing 1/2 inch screen at the storm drain inlets.	healthful, safe GEPA require drainage inlets	, and sanitary lear s the installation o	f such screen under the objects from entering	Address and rectify immediately in into compliance with the law.	order to come